

EBOX, DIN PC Series Kernel Source/ Header File

Title	File
2.6.34.11	linux-2.6.34.11.tar.bz2
2.6.34.10 Ver.1.2	linux-source-2.6.34.10-vortex86-sg_1.2_all.deb
2.6.34.1	linux-2.6.34.1-vortex86-sg.tar.bz2
2.6.30-apm Ver.1.1	linux-source-2.6.30-vortex86mx-apm_1.1_all.deb
2.6.32-21	linux-headers-2.6.32-21-vortex86_2.6.32-21.32_i386.deb
2.6.30 Ver.1.1	linux-source-2.6.30-vortex86mx_1.1_all.deb
2.6.30	linux-2.6.30-vortex86mx.tar.bz2

EBOX, DIN PC Series Kernel Configuration/ Patch

Title	File
Kernel 2.6.30	vortex86mx_patch_and_config_2.6.30
Kernel 2.6.34	config-2.6.34-vortex86-sg-r1
Kernel 3.2	patch_r6040_for_kernel_3.2 (R6040 MDIO unique name and delay)
EHCI reset (Coreboot)	patch-3.10.55-vex_ehci (for EBOX-3100-VGA, and 3350EX Series only)